McGRATH AIRPORT

Contents:

- A Pavement Strength Form showing project history, latest Pavement Condition Index (PCI) data, pavement strength ratings (if available) and other useful information
- A Pavement Condition Survey PCI Sample Unit Layout Plan
- PCI maps showing as-measured and predicted pavement conditions
- Age map showing pavement age as of January 2003
- A Branch PCI Condition Report
- A Section PCI Condition Report

Airport Information:

 Location: McGrath Airport is located in Southwest interior Alaska running along the Kuskokwim River on the west side of town. The airport is approximately 125 air miles southwest of Mt. McKinley.

District: Matsu District, Central Region

Airport Manager: Mike Fleagle
District Maintenance Manager: Kurt Devon
Pavement Surface: Asphalt Concrete

• Last Pavement Construction:

- 2001: Runway 16-34 reconstruction, Taxiways and East Ramp paving

• Pavement layout: 2 Runways 16-34 and 7-25, 6 taxiways and 3 Aprons.

• Design Aircraft: Boeing 737-100

2001 Enplanements: 5,515
Airport Class: Non-Primary
Last pavement condition survey: June 3, 2003
Next planned pavement condition survey: 2006

• 2003 reported pavement maintenance and/or changed conditions:

- No reports

Recommendations:

- Crack seal and patch as needed
- Reconstruct:
- o West end of R/7-25
- o Taxiway B
- North Ramp